#### FOREICS STRVICE DISPATCH

American Embassy Bons

FECT

984

THE DEPARTMENT OF STATE CERP 195": D WITT A.L. B.L

Rmlez RA-1 E-1 1RC-8 L-2 FAA-5 Com-10 Cab-6 any Cop-10 Mary -

Monthly Report Berlin Air Safety Center (BASC) April 1959.

The following is shetracted from the April report of the U.S. Element of the BASC, received in the Embassy May 7, 1959. One copy of the full report is filed with the Avietion Division, Department of State.

## 1. ITEMS OF GENERAL INTEREST

(a) A C-130 flight from the Federal Republic to Berlin and return on April 15 was the "high point" of the month. Both the Soviets and Americans mainteined the positions taken during the initial C-130 flight in March 1959. The Soviet Element, BASC, protested the eltitude of the flight and the U.S. Element, BASC, protested the action of the Soviet fighter eircraft. The Soviet Controllers adopted the ettitude of not even wanting the flight plan since their government took no responsibility for the safety of the flight. This stated position did not, however, prevent them from relaying information copied from the flight plen passed to them nor from repeatedly querying the American Controller shout the eircreft's position and eltitude. The Soviet Controller asked why the Soviet government's guarantee was not necessary and yet the Soviet government was still responsible. The U.S. Chief Controller advised the Soviet Controller that the right to fly the corridors without prior notice was made by previous agreement and that a guarantee of safety of flight is not necessery. Flight plens ere pessed to the Soviets only to help them in separeting treffic.

(b) On 21 April the Soviete egain issued the Western Controllers an edvisory on Soviet treffic in the vicinity of the sir corridors. Generally the advisory was of the seme type issued by the Soviets on 13 March 1959. This time however, there was no request to sivise the Soviets if western sircreft needed eny eltitudes above 10,000 or below 2,500 feet. There was amore epecific statement as to Soviet traffic though. The Soviet Interpreter stated that there would be treffic crossing the corridors et 900 meters and that the Soviets would provide further information. He then requested that the Western Controllers ettempt to prevent eny "undus" eltitude changes during the period covered by the edvisory. Both the British and American Controllers then informed the Soviet Interpreter that they would continue to provide him with flight information in the normal menner. On three occesions the Soviets informed the American Controller of traffic crossing the South Corridor. Each advisory

CONFIDENTIAL

ACTION COPY - DEPARTMENT OF STATE

The action office must return this permanent record copy to RM/R files with an endor-

62

4

OI on

Ö

consisted of the estimated time of crossing, the altitude (900 meters in each case) and the position of the processing. The first processing was at Actnes, the next at Derbst and the last approximate. It was not read of Tempelhof. It was the impression of the American Copty Her that the Soviets were deliberately moving the propolings places and aller to the Beriin Control Zone in order to see where and when it would be se elast. for him to take action to move western traffic to avoid their traff. . At no time did the American Controller take action involving the Sovieta. he e erted Berlin ATC to watch for unusual traffic in the corridors and closely monitured his flight plans for any possible conflicts. The alerting of Berlin ATC was done without the knowledge of the Soviets. Despite one query concerning the position of a PAA Clipper and a few muttered comments suggesting the sterting of Berlin ATC, at no time did the Soviets sttempt to pass a formal fright plan to the America: Controller. No siviscries were given to the British Controller although the original warning covered all three corridors. Berlin ATC did not observe any unusual traffic in the corridors. This was very probably due to the low altitude of the crossingand their dietance from Berlin. There were no reports of unusual activity from Western aircraft in the South Corridor.

- (c) On 23 April the Three Western Fowers passes supremiss for the Sortet Foreign Minister to overfiy the Refers Impublic of Commony on route to and from the George Conference scheduled for 11 May 1999. Also included to the Common Conference scheduled for 11 May 1999. Also included conference to the Federal Republic for the East German schiours to the Conference of the Common Conference on the Conference of the Common Commo
- (a) 0m 20 April the Three Vestern Powers received on monwer to the approvate of 24 April. The Software enhancished receipt of the Pietters. They then informed the Western Powers with the Soviet delagation. They stated it will know fact that there would be on independent delegation from the German Memoratic Republic going to the conference in Seener on 11 May 1959.
- (e) On 3 April the Sowiet Interpreters twice made remarks indicating they felt they should be given prior notice of flights in the corridors. The American Controller pointed out to them that no each requirement exists in the Four Power Agreements. He etsted we would continue to pass flight place as soon se eveilable see we have done in the peat.

(f) On two occasions during April, it. Shustiski requested information from the American Controller whout the working of the ICAO teletype network. He wiso requested the loan of the ICAO identifier book. His request was honored as it especied to stee from an equal need relating to Soviet flights to the Genera Foreign Ministers Conference.

CONFIDENTIAL

- (a) On 25 April the British Controller told the American Controller that a few Amp previously the Source Controller, Captain Roteino, had remarked that this tour of duty in Berlin Last bere extended for one year, the approximation of the controller of the past in stating that be was leaving the first of May 1999. Be appeared quite unmappy should this devolution.
- (a) On 36 April Lit. Krimahin was observed by the American Controller to note "2.5 10.0% or a WP loved Fight time. Be then sidenly excitence," On I'm sorry;" and struck out the notation. It can only be assumed at this time that the Soviets now realize we shoom the 10,000 foot limit in the Berlin Control Zone. Previously they haveplaced restrictions on local VFF on such blass. As of this voticing, no more restrictions have been placed on such blass.
- (i) On 5 occasions during April there have been difficulties with pilots attempting to file at altitudes above 10,000 feet in the corridors. A Polish sircraft filed for 15,000 feet. The British Controller advised London via teletype that there would be an indefinite delay. Berlin ATC was advised to clear the aircraft at some altitude below 10,000 feet. This was done with the Soviet Controllers present. A British Argonaut requested 15,000 feet inbound in the South Corridor. American Controller sivised Berlin ATC there would be an indefinite delay but that 10,000 feet was immediately available. After conferring with British Controller, the American Controller told Berlin ATC the aircraft could enter the corridor at 1,000 feet on top. Frankfurt ATC advised that this could not be done since the Federal Rapublic does not recognize this type of clearance at night. The aircraft flew the corridor at 10,000 feet. A PAA Clipper requested 15,000 feet inbound in the South Corridor. The American Controller informed Berlin ATC that the mircraft could have 9,000 feet or 1,000 feet on top. The pilot changed to 1,000 on top and then asked Frankfurt ATC over the air why he had been cleared at 1,000 on top and not at 15,000 feet. He was referred to the American Element, Berlin Air Safety Center. This affair was subsequently handled by Mr. Deason, U.S. Administrator at Tempelhof. An Air Force sircraft requested 12,000 feet in the South Corridor after originally filing for 5,000 feet. The American Controller told Frenkfurt ATC to inform the pilot that 9,000 feet was cleared for him. Frankfurt Control stated they had tried to give the pilot a lower altitude but that he would not accept it and could not state why he needed 12,000 feet. The American Controller then had the pilot informed there would be an extended dalay. The Air Force aircraft then accepted a lower altitude. Another PAA Clipper requested 11,000 feet imbound in the South Corridor. The American Controller offered 9,000 feet. The pilot requested 10,000 feet which was approved.
- (3) On 2 occesions during April the Soviets complained to the Asertian Controller show teincreft (Figure over Soviet saffreids within the Berlin Control Ison. Nother complaint resulted in further action by the Soviets. In setther case did the aircreft violate the antity some of the Soviet significant or special to the second instance the Asertica Controller specifically informed that the Soviet significant or special to the Soviet significant of the Soviet significant significant

CONFIDENTIAL

NNO 877419

(x) April frond the Soviet Controllers making 26 inquiries about alledgedly uncoordinated traffic or backing border crossing times of Western extraft. Num of the allegations was proven correct.

(1) On the 20 of April the Soviet Interpreter informed the Western Controllers that there would be a Soviet flight from Mosor to Geneva on 6 May returning to Moroov T May 1999. There would be a second flight on 9 May returning the Second Y May 1999. There would be a second flight on 9 May returning the Second Y May 1999. There would be a second flight on 50 May return the Second Y Temaportation. For Soviet delegation to Geneve Foreign Ministers Conference. On 30 April the Soviet Chief Controller delivered the formul systiem overflight request to the Western Controllers. Two hours letter the Soviet Interpreter tool the American Controllers. Two hours letter the Soviet Interpreter tool the American Controllers. Two hours letter the Soviet Interpreter tool the American Controllers. Two hours letter the Soviet interpreter to this vertice, nothing her been seld to the Soviets in regard to this vertice, nothing her been seld to the Soviets in regard to this request, elibough Mr. Punkerthy received notice from Son that the requested route was approved. Formula notification is sweiting.

# 2. PROTESTS

(e) On 4 April the U.S. Chief Controller passed a reply to the Soviet protest of 27 March. The reply rejected the Soviet contention that corridor regulations preclude flights at high eltitudes. The U.S. did not agree that the flight of the C-130 violeted existing rules for corridor flights. The Soviete were reminded of the U.S. lettere of June 6 end September 8, 1958 edising them that the U.S. did not recognize eny limitation of flight eltitudes in the corridors. They were elso edvised that flights et different eltitudes do not require different procedures, that flight eltitudes are governed by meteorological conditions and operational characteristics of the eircraft involved end that improved navigational facilities provide adequate safety for such flights. On the other hand the ection of the Soviet fighters not only violated existing corridor regulations but also intentionally created the very sefety hezard about which the Soviets were concerned. The U.S. recognized the mutual interest in sefety of flight in the corrider and stated these interests would be fulfilled if the Soviete ected i ence with existing corridor regulations and used the information for them by the Western Controllere to separate their traffic from traffic. It was elso pointed out that flight information on this culer flight was passed to the Soviets over one hour prior to the : entering the corridor. The U.S, rejected the Soviet contention that a violation on the part of the U.S. occurred end steted that the implied threat of "undesirable consequences" by the Soviets was entirely unwarrented. Furthermore. United States eigereft would continue to fly through the corridors at whatever eltitude was eppropriets and with due notification of the Soviet suthorities.

(b) Also on 4 April the Soviet Interpreter delivered en orel protest concerning the flight of AF 92659 which ellegadly flew showe 10,000 feet in the South Corridor. The Soviets requested action be taken to prevent violetion of the 10,000 foot limit which has been established by long time practice.

CONFIDENTIAL.

NNS 877419

- (c) On 7 April the American Controller delivered at oral reply to the Sowiets desping their allegation that AF 03295 violated the boundaries of the South Corridor on 30 March 1959.
- (4) On 10 April the U.S. Chief Controller comity replied to the Soviet oral protect of April concerning #F 96605. The Soviets were informed that the sirrorit was on a TW clearance viscents the plicit is responsible for unilateral listention of sirrorit could be understood to the control of the Soviet of the Control of the Control of the Soviet will be understood that a violation occurred. The U.S. Chief Controller then strongly protected the sction of the Soviet Wild Signatus which harmsets affect that the strongly protected the sction of the Soviet Wild Signatus which harmset affect that the strongly protected the sction of the Soviet Wild Signatus which harmset affect that the school of the Soviet Wild Signatus with the school of the Soviet Wildeline of corridor regulations as well as eccepted stendards of eart flying.
- (e) on 15 April the Soviel Interpreter made on oral protest to the British Controller. The protest conserved the violation of the East German border by two unidentified jet fighters from the British Zone of Germany. The Soriets protested, requested sessures be taken to prevent recurrence and stated such violations could have undestrable consequences for which the British would be entirely remonstible.
- (1) On 16 April the U.S. protested the deliberate, unwarranted and deagerous heresement of a C-19 on route to and from Berlin. The Sorieta were remainded that they were duly notified of the flight in the customery amoner. The U.S. insisted again that the Sorieta take action to insure that flights operating in the sir corridors in accordance with Quadripartite agreements will not be subjected to dangerous and unwarranted hereasons. The Sorieta were winded that the United States will joid them executed.

  The Sorieta were deleted that the United States will joid them executed the corridors are assembled for will religiously the corridors.
- (g) Also on the 16th of April the British Chief Controller made an oral reply to the Soviet oral protest or 15 April contening the violation of the East German Border by jets from the British Zome of Germany. The British edmitted the violation, which caused by radio difficulties, and stated that action was being taken to prevent a recurrence.

#### 3. UMUSUAL INCIDENTS

- (a) On 16 April the British Controller informed the Soviet Controller that a British Tork, in the Center Corridor, had had two Soviet twin yet eigeneft pass across its mose within 300 feet. The British Controller took non further ection. A few someth later the Soviet Interpretar requested the position of the incident and after approximately %9 ninutes he edvised the British Controller that the Incident was being investigates.
- (b) On the 26th of April the Soviet Interpreter requested that the Aperican Controller confirm the eltitude of PAA 680, inhound in the South Corridor. The American Controller obacked and replied that the eigenful was just leaving 7.000 feet for 3 000 feet. This was passed to Karishorst.

CONFIDENTIAL

NNO 877419

A few amounts later the Soviet Interprets gets requested a confirmation of PAA 550's estitution. He stated that he able here informed the the attractiff was at 3,000 maters. The American Controller again checked beright and confirmation of the confirmation of PAA 650's confirmation attraction of the confirmation of PAA 650's confirmation attraction of the confirmation of PAA 650's confirmation attraction of the confirmation of PAA 650's confirmation of the confirmation of PAA 650's confirmation of the confirmation of PAA 650's confi

- (c) On 20 April Captain Kotenko passed the following remark to the American Controller when queried as to what written agreement the C-130 flights had violated. "Just wait, we have not had our last word, we will show you this is dangerous business." Be also stated the subject of these frights will be discussed at the Foreign Ministers Conference, 11 May 1059.
- (4) On 18 April Berlin Redar observed an apparent corridor violation by PAA 607, outbound in the North Corridor. The streraft was steered back into the corridor by Berlin. As of this date there has been on indication that the Sovieta are aware of the deviation. It appears probable that the cause of the deviation was thunderstored.
- 4. SPECIAL FLIGHTS
  - (a) PAA M-90905 Berlin to Hannover, Cargo. 24 April, 1959.

### 5. FLIGHT FIGURES

During April 1559 there were a total of 3,264 flights in and out of Berlin vis the air corridors, 1122 of which were vis the U.3 (South) corridor. There were 64 flights in the local area. Total U.5. shiftsry sircraft flying to and from Berlin via corridors was 357. There were no accidents.

For the Charge d'Affairea ad interim:

William C. Ockey
William C. Ockey
Counselor of Embeasy for
Economic Affairs

Distribution: USBER BASC USAFE ADVON CINCUSAFE LONDON PARIS AIRA POL E:OD E:TRC 2

CONFIDENTIAL

1876

NNO 8724/5

. UU ... 2/2